

2017		
Sunshine Bay 2050	Bedrock (no	on-erodible)
Deterministic erosion/recession hazard lines — 2065		
2100		Figure I.12



lowering of the beach profile from entrance scouring. Note 3: The shape of hazard lines not located at the seawall is hypothetical only and requires further detailed assessment beyond the scope of this study.

Malua Bay existing seawall	2017	Watercours	se instability region
5% encounter probability	2050	Seawall	
. ,	2065	ocawaii	
Probabilistic erosion/recession hazard lines	2100		Figure I.13



lowering of the beach profile from entrance scouring. Note 3: The shape of hazard lines not located at the seawall is hypothetical only and requires further detailed assessment beyond the scope of this study.

Malua Bay existing seawall	2017	Watercours	se instability region
1% encounter probability	2050	Seawall	
	2065	Countain	
Probabilistic erosion/recession hazard lines	2100		Figure I.14



Malua Bay no seawall	2017	Watercours	e instability region
1% encounter probability	2050		
	2065		
Probabilistic erosion/recession hazard lines	2100		Figure I.16



Malua Bay no seawall	2017	Watercours	se instability region
5% encounter probability	2050		
	2065		
	2100		Figure I.15